

3 December 2013

The fiber connection at the S2 switch in the lofar container was apparently loosened: there was packet loss between Bonn and the LOFAR container that increased with packet size. Re-seating the connector removed this problem.