

Remarks

bad antenna DV10 (see scan 1 below)

strange behaviour on scan 2

Command





```
18:39:50 VLBITestObs.py -b 3 -N 3 -d 10 -i 1 -Q 4 -T  
--app-comp="DA63,DA51" -R DA52 -s 1337-129 --app-clone-bb=3 --app-faker  
40,2,8 --app-numSWs 4
```

Scans

- 1: <uid://A002/X91023f/Xd8>
- 2: <uid://A002/X91023f/Xdb>
- 3: <uid://A002/X91023f/Xde>

Scan 1





Including DV10



ExecBlockUID: uid___A002_X91023f_Xd7
 Scan: 1
 DataUID: uid://A002/X91023f/Xd8
 Excluded: [11]

Efficiencies
 unphased (pol 0/1): 10.24% / 11.11%
 phased (pol 0/1): 97.47% / 96.01%





Excluding DV10



ExecBlockUID: uid___A002_X91023f_Xd7
 Scan: 1
 DataUID: uid://A002/X91023f/Xd8
 Excluded: [11, 8]

Efficiencies
 unphased (pol 0/1): 10.25% / 11.13%
 phased (pol 0/1): 100.00% / 100.00%

Scan 2







ExecBlockUID: uid___A002_X91023f_Xd7
 Scan: 2
 DataUID: uid://A002/X91023f/Xdb
 Excluded: [11, 8]

Efficiencies

unphased (pol 0/1):	12.68%	/	45.15%
phased (pol 0/1):	89.88%	/	83.12%

Scan 3



ExecBlockUID: uid___A002_X91023f_Xd7
 Scan: 3
 DataUID: uid://A002/X91023f/Xde
 Excluded: [11, 8]

Efficiencies

unphased (pol 0/1):	41.12% / 58.46%
phased (pol 0/1):	100.00% / 100.00%